





FIG. 2



6/24

FIG. 6



9/24

FIG. 9





FIG. 13



22/24

FIG. 22A

(PRIOR ART)






FIG. 22B

(PRIOR ART)



23/24

FIG. 23
(PRIOR ART)



24/24

FIG. 24A

(PRIOR ART)

DRIVE CURRENT OF FIRST
SENSOR PROBE




FIG. 24B

(PRIOR ART)

DRIVE CURRENT OF
SECOND SENSOR PROBE




FIG. 24C

(PRIOR ART)

GROUND CURRENT




FIG. 24D

(PRIOR ART)

GROUND CURRENT AMPLITUDE VALUE (RELATIVE VALUE)




FIG. 24E

(PRIOR ART)

MEASUREMENT VALUE
OF FIRST SENSOR

LARGE INTERVAL

MEASUREMENT VALUE
TRUE VALUE

ERROR




FIG. 24F

(PRIOR ART)

MEASUREMENT VALUE
OF SECOND SENSOR

LARGE INTERVAL

MEASUREMENT VALUE
TRUE VALUE

ERROR

